



2900 Selma Highway  
Montgomery, AL 36108 USA  
Tel: 334-386-5400 Fax: 334-386-5450

# SERVICE LETTER

SERVICE LETTER No. 223

## Turbocharger 465398-2 BOM Update

---

### 1. Planning Information

#### A. Effectivity

- (1) AeroForce Turbocharger 465398-2 is affected by this Service Letter (SL).

**WARNING:** DO NOT USE OBSOLETE OR OUTDATED INFORMATION. PERFORM ALL INSPECTIONS OR WORK IN ACCORDANCE WITH THE MOST RECENT REVISION OF THIS SERVICE LETTER. INFORMATION CONTAINED HEREIN MAY BE SIGNIFICANTLY CHANGED FROM EARLIER REVISIONS. FAILURE TO COMPLY WITH THIS SERVICE LETTER OR THE USE OF OBSOLETE INFORMATION MAY CREATE AN UNSAFE CONDITION THAT MAY RESULT IN DEATH, SERIOUS BODILY INJURY, AND/OR SUBSTANTIAL PROPERTY DAMAGE. REFER TO THE AEROFORCE WEBSITE, [WWW.AEROFORCE.AERO](http://WWW.AEROFORCE.AERO), FOR THE MOST RECENT REVISION LEVEL OF THIS SERVICE LETTER.

#### B. Concurrent Requirements

- (1) None

#### C. Reason

- (1) This Service Letter serves as a notification to the field of a part number typo correction.
  - (a) This typo correction is a permanent change and will be reflected at the next revision level of the referenced manual.

#### D. Description

- (1) This SL corrects a typo currently found in HET Manual 400600-0000 Rev. E and prior FAA approved revisions.

#### E. Approval

- (1) This Service Letter has been approved by Hartzell Engine Tech LLC.

#### F. Manpower

- (1) No additional man-hours are required.

# SERVICE LETTER

## SERVICE LETTER No. 223

### **Turbocharger 465398-2 BOM Update**

---

#### G. References

- (1) HET Manual 400600-0000, *Aircraft Turbocharger Maintenance and Overhaul*, Rev. E or prior FAA approved revision.
  - (a) Pg. 5-250-01, change ITM #8, Turbine Housing P/N 409752-34 to P/N 409752-64
  - (b) Pg. 5-250-01, change ITM #10 to Compressor Wheel and P/N to 409826-10

#### H. Weight and Balance

- (1) No Change

### **2. Materials Required**

A. N/A

### **3. Contact Information**

A. Contact HET Product Support for all communications regarding the technical content of this Service Letter.

- (1) Phone +1.334.386.5400 (Option 2)
- (2) Fax +1.334.386.5450
- (3) E-mail at [techsupport@hartzell.aero](mailto:techsupport@hartzell.aero)
- (4) Address

Hartzell Engine Tech LLC - ATTN: Product Support  
2900 Selma Highway  
Montgomery, AL 36108  
USA