



2900 Selma Highway
Montgomery, AL 36108 USA
Tel: 334-386-5400 Fax: 334-386-5450

Service Letter

Letter No. 019B

Issue Date: May 20, 2006

REISSUE AND SUPERCEDEURE OF TURBOCHARGER OVERHAUL MANUAL

Hartzell Engine Technologies has reissued and superceded the Turbocharger Overhaul Manual mentioned in the previous issue of this service letter. Hartzell Engine Technologies Turbocharger Overhaul Manual P/N400600-0000 supercedes the Garrett/Honeywell Manuals TP20-0128, Rev. B and Rev. C, issued September 2001 and all previous publications including but not limited to prior Garrett/AirResearch Turbocharger Overhaul Manuals. This manual also supercedes the RAJAY Aircraft Turbocharger Overhaul and Test Manual P/N 600999-0000, issued November, 1998 and all previous RAJAY/RotoMaster Aircraft Turbocharger Overhaul Manuals for the 600 Series of Turbochargers.

This manual contains select NEW Hartzell Engine Technologies and PMA'd turbochargers and is published for the information and guidance of all personnel responsible for overhauling, maintaining, and testing of Garrett/AirResearch and RAJAY style turbochargers.

This release (P/N: 400600-0000 Rev. New) does not contain the following part numbers since PMA is not held on these units:

404350-1 (629844-1)	406610-27 (N/A)
404830-1 (73895)	408250-4 (4885-1)
406110-7 (LW-13309)	465292-1 (C295001-0301)
406330-1 (N/A)	465448-4 (C295001-0203)
406610-3 (N/A)	

Any of the above mentioned units may be repaired in accordance with the earlier Manual TP20-0120 dated August 15th, 1985. This manual, while it is no longer revised, is still accepted for the purpose of maintenance and repair of the excluded turbochargers.

With the release of this replacement manual, customers that have obtained the earlier Manual TP20-0128 rev. B or C within the last year, may obtain the new P/N 400600-0000 manual at no cost. To obtain the new manual at no cost, customers must be on record and provide the manual serial number along with a copy of the original invoice of purchase. This offer is good for sixty (60) days from the issue date of this service release.

Manual P/N 400600-0000 may be purchased direct through Hartzell Engine Technologies customer service. Contact (334) 386-5400 or (334) 386-5450 FAX.